







H=2100 **015** **017**
 H=2400 **016** **018**
019




Ø1500 **044**
 Ø1650 **045**
 Ø1800 **046**




Ø1500 **047**
 Ø1650 **048**
 Ø1800 **049**

H=2100 **015** **017**
 H=2400 **016** **018**
019

040




n.	code




n.	code	
1	SBC0029609	
2	S340052793Z	
3	S340006293Z	
4	SCC0001969	
5	SCC0000578	
6	S340023593Z	
7	SBC0006038	
8	S340017593Z	
9	S340000493Z	
10	S340021993Z	
11	SBA0018033T	
12	S340001593Z	
13	S3401776ZZZ	
14	SBA0017753V	
15	SCA0002298	
16	S340514093A	
17	SBC0028338	
18	SBC0026666V	
19	SBA0017727V	
20	S340078293Z	
21	SBA0016355	

IDM 51005701700




n.	code	
1	SBC0029609	
2	S340052793Z	
3	S340006293Z	
4	SCC0001969	
5	SCC00000578	
6	S340023593Z	
7	SBC0006038	
8	S340017593Z	
9	S340000493Z	
10	S340021993Z	
11	SBA0018033T	
12	S340001593Z	
13	S3401776ZZZ	
14	SBA0017383V	
15	SCA0002299	
16	S340514093A	
17	SBC0028338	
18	SBC0026666V	
19	SBA0016961V	
20	S340078293Z	
21	SBA0016355	

IDM-51005701800




n.	code	
1	SBC0029609	
2	S340052793Z	
3	S340006293Z	
4	SCC0001969	
5	SCC00000578	
6	S340023593Z	
7	SBC0006038	
8	S340017593Z	
9	S340000493Z	
10	S340021993Z	
11	SBA0018033T	
12	S340001593Z	
13	S3401776ZZZ	
14	SBA0017961V	
15	SCA0002038	
16	S340514093A	
17	SBC0028338	
18	SBC0026666V	
19	SBA0017964V	
20	S340078293Z	
21	SBA0016355	

IDM-51005701900





n.	code
1	S3401776ZZZ
2	S340023593Z
3	S340017593Z
4	S340006293Z
5	S340001593Z
6	S340159993Z
7	S340078293Z
8	S340514093A
9	SBA0016355
10	SBA0019403V
11	SBC0006038
12	SBC0026666V
13	SBC0028338
14	SBA0019406V
15	SCA0002403
16	SCC0000578
17	SCC0001969

IDM-51005700100




Ø2200

004





n.	code	
1	SBA0006535*	
2	S330221593A	
3	SBA0004851*	
4	SBC0010239T	
5	S340005393Z	





n.	code	
1	S340003692Z	
2	S350051593Z	
3	S3210008693A	
4	SBC0018979T	
5	S3401483ZZZ	
6	SCA0001553 UL / CSA	
6	SCA0002077 230/415V - 440V	
7	SCA0001552	
8	SBC0026739	

IDM-51001701600




n.	code
1	SBA0010962
2	S340000393Z
3	S340014492Z
4	S332102593A
5	S340012393Z
6	S340078293Z
7	S340017293Z
8	S440857347A
9	SBC0017580
10	SCA0001529
11	S340028093Z


IDM-51005700200



n.	code
1	SBA0012056
2	S340000393Z
3	S340012393Z
4	S340065593Z
5	S340174993Z
6	S340005893Z
7	SBA0012055
8	SBC0020190V





n.	code	
1	S471135200A	
2	S321680847A	
3	SBA0017986	
4	S340190493Z	
5	S320891747A	
6	S340065093A	
7	S340021993Z	
8	S340198093Z	
9	SCC0002058	
10	S340006193Z	
11	S4204303ZZZ	
12	SCC0000047	
13	S320698993A	
14	S321680547A	
15	S340198093Z	
16	S3401776ZZZ	
17	S321680547A	
18	S3403390ZZZ	
19	S331821400A	
20	S340297593Z	
21	S340006293Z	
22	S340174993Z	
23	SBC0012058	
24	S340016093Z	
25	S340017593Z	
26	S340028093Z	
27	S340012393Z	
28	SBC0012017	
29	S340514093A	
32	S340524800A	
33	S340000493Z	
34	S340021993Z	
35	S340040393Z	
36	S4204254ZZZ	
37	S370033693A	





n.	code	
1	S470896000A*	
2	S331452492C	
3	SBC0000633*	
4	S3402779ZZZ	
5	S3402778ZZZ	

51001701700





n.	code	
1	S470993500A	
2	S310182100A	
3	S320750800A	
4	S310173800A	
5	S331825000A	
6	S3403039ZZZ	
7	S331824900A	
8	S340073593Z	
9	S331824792A	
10	S340073593Z	

51001701800





n.	code	
1	S470993000A	
2	SCA0000168	
3	S320742147A	
4	S340012493Z	
5	S331823893A	
6	S331822793A	
7	S340101693Z	
8	S320605693A	
9	S3400017ZZZ	
10	S340004793Z	
11	S340304092Z	
12	S3403011ZZZ	
13	S3403043ZZZ	
14	S331823900A	
15	S340077493Z	
16	S340000392Z	
17	S340011293Z	
18	S330491693Z	
19	S3401240ZZZ	
20	S331824500A	
21	S3401577ZZZ	
22	S340006892Z	
23	S3400017ZZZ	
24	S331824600A	
25	S331824200A	
26	S440639700A	
27	SCA0000168	

51001701900




n.	code
1	S470993200A
2	S340006193Z
3	S320743500A
4	S370033500A
5	S3400141ZZZ
6	S310173700A*
7	S340002393Z
8	S440639000A
9	S340011293Z




n.	code
1	SBA0007313
2	S3210008693A
3	SCA0001030
4	SBC0010739
5	S340220592Z
6	S340012293Z
7	S440857347A
8	S350051593Z
9	S340002193Z
10	S340017593Z
11	S340012493Z
12	SBC0012393T
13	S3401483ZZZ
14	S3400014ZZZ
15	S332981800A
16	S340003692Z
17	SBC0012531T
18	SBA0007579T
19	SBC0012507T
20	SBC0012508T



51001702100



n.	code	
1	S340000293Z	Label No label
2	S340004393Z	
3	S340017593Z	
4	S340006293Z	
5	S340342293Z	
6	SCA0002316	
7	SCA0000133	
8	S340022993Z	
9	S340093493Z	
10	S340223393Z	
11	S321635293A	
12	S340223393Z	
13	S3403210ZZZ	
14	S3403414ZZZ	
15	S340511300A	
16	SCA0000302	
17	S380582600A	
18	S380594400A	
19	S380594800A	
20	S380594900A	
21	SBA0019004	
21	SBA0018266	
22	SBA0018853	
23	S340513993A	
24	SBC0027438T	
25	SBC0030276	
26	S340514093A	





n.	code	
1	S340000293Z	Label No label
2	S340004393Z	
3	S340017593Z	
4	S340006293Z	
5	S340342293Z	
6	SCA0002316	
7	SCA0000133	
8	S340022993Z	
9	S340093493Z	
10	S340223393Z	
11	S321635200A	
12	S340223393Z	
13	S3403210ZZZ	
14	S3403414ZZZ	
15	S340511300A	
16	SCA0000302	
17	S380582600A	
18	S380594400A	
19	S380594800A	
20	S380594900A	
21	SBA0019004	
21	SBA0018266	
22	SBA0018858	
23	S340513993A	
24	SBC0027438T	
25	SBC0030284	
26	S340514093A	




n.	code
1	SBA0008112
2	SCA0000108
3	S340012393Z
4	S340028393Z
5	SBC0000499T
6	SBC0000502
7	SBC0000500V

51001702200





n.	code	
1	S471428200A H=2100 mm	
1	SBA0003451 H=2400 mm	
2	SBC0000501T	
3	S310151200A* H=2100 mm	
3	S310197100A* H=2400 mm	
4	S332950093A	
5	S331907681A	
6	S332945592A	

51001702300





n.	code	
1	S3805202ZZZ	
2	S340017593Z	
3	S340005193Z	
4	SBC0027643V	
5	S3801649ZZZ	

51001702400





n.	code
1	SBA0014193V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027769V
17	S340002693Z
18	SBC0027636
19	S340000193Z
20	S340004393Z
21	S340514093A
22	SBC0008060T
23	S340014293Z
24	SBC0006420
25	S332207492A
26	SBC0028564V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z





n.	code	
1	SBC0008523T	
2	SBA0005213	
3	SBC0008524T	
4	S340012393Z	
5	S340058493Z	
6	SCA0001050	
7	SBC0011889T	
8	S340010492Z	
9	S321205693A	
10	SBA0005198	
11	SBC0011888	
12	SBC0011885	
13	SBC0011879T	
14	S340038293Z	
15	SBC0011887T	
16	SBC0011560	
17	S340083093Z	
18	SBC0011559T	
19	SBC0011883	
20	SBA0007291	
21	S310094100B*	
22	S321256098A	
23	S320699093A	
24	S340090293Z	
25	SBC0008060T	

51001700710






n.	code	
1	SBA0017660	
2	S340006193Z	
3	S340083992Z	
4	SBC0026716V	
5	SBC0027637T	

51001702500





n.	code
1	SBA0014193V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027769V
17	S340002693Z
18	SBC0027636
19	S340000193Z
20	S340004393Z
21	S340514093A
22	S340220292Z
23	S340014293Z
24	S300144499A
25	S332207492A
26	SBC0027542V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z



51001700800





n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	SBC0008523T
14	SBC0008524T
15	SBA0005213
16	S340006293Z
17	SBA0009201
18	S340028393Z
19	SBC0014327T
20	S340180493Z
21	S340033593Z
22	S3311811ZZZ
23	S340018892Z
24	S350240892Z
25	S350235792Z
26	S370025193Z
27	S450544993Z
29	S42004333ZZZ*
31	S430489ZZZ
32	S4304890ZZZ
34	S340040092Z
35	S320282593Z
36	S4305051ZZZ
37	S3450006ZZZ
38	S4304891ZZZ
39	S310177700A*
40	S331910092A



n.	code	
1	SBA0014193V	
2	S320926498A	
3	S332208492A	
4	S332208592A	
5	S340012393Z	
6	S340129293Z	
7	S340028393Z	
8	S340091093Z	
9	S370031898A	
10	S310071605Z	
11	S332207592A	
12	S320926993A	
13	S310195800A	
14	S340006293Z	
15	S340223393Z	
16	SBC0027769V	
17	S340002693Z	
18	SBC0027636	
19	S340000193Z	
20	S340004393Z	
21	S340514093A	
22	S340220292Z	
23	S340014293Z	
24	S300144499A	
25	S332207492A	
26	SBC0027542V	
27	SCA0002198	
28	SBC0028129	
29	S340055893Z	
30	S340034193Z	
31	S340017593Z	
32	S340023593Z	





n.	code
1	S340180493Z
2	S340028393Z
3	S340006193Z
4	S340012393Z
5	S340006293Z
6	S340058493Z
7	S340032993Z
8	S340033593Z
9	S3311811ZZZ
10	S331910092A
11	S340018892Z
12	S350235792Z
13	S350240892Z
14	S350265000A
15	S370025193Z
16	S4204190ZZZ
17	S4204333ZZZ
18	S4304890ZZZ
19	S4305051ZZZ
20	S450544993Z
21	SBA0005213
22	SBA0009201
23	SBC0008523T
24	SBC0008524T
25	SBC0014327T






IDM-51005700800

n.	code	
1	SBA0009961	
2	S340010492Z	
3	S340090293Z	
4	S340038293Z	
5	S320699093A	
6	S321205693A	
7	S321256098A	
8	S340083093Z	
9	SBA0005198	
10	SBC0008060T	
11	SBC0011559T	
12	SBC0011560	
13	SBC0011879T	
14	SBC0011882	
15	SBC0011883	
16	SBC0011885	
17	SBC0011887T	
18	SBC0011888	
19	SBC0011889T	
20	SBC0029978	
21	SCA0001050	





n.	code	
1	SBA0014193V	
2	S320926498A	
3	S332208492A	
4	S332208592A	
5	S340012393Z	
6	S340129293Z	
7	S340028393Z	
8	S340091093Z	
9	S370031898A	
10	S310071605Z	
11	S332207592A	
12	S320926993A	
13	S310195800A	
14	S340006293Z	
15	S340223393Z	
16	SBC0027769V	
17	S340002693Z	
18	SBC0027636	
19	S340000193Z	
20	S340004393Z	
21	S340514093A	
22	SBC0008060T	
23	S340014293Z	
24	S300144499A	
25	S332207492A	
26	SBC0027542V	
27	SCA0002198	
28	SBC0028129	
29	S340055893Z	
30	S340034193Z	
31	S340017593Z	
32	S340023593Z	

IDM-51005702800





n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	SBC0008523T
14	SBC0008524T
15	SBA0005213
16	S340224593Z
17	S340006193Z
18	SBA0001946
19	S332305981A
20	S340023493Z
21	S450544893Z
23	S321006883A*
24	S42004332ZZZ
25	SBA0006068
27	S340019192Z
28	S332306393A
29	S340010492Z
30	S320770393A
31	S4305046ZZZ
32	S310177700A*
33	S340028393Z
34	SBC0009454T
35	SBC0029352T
36	S340017793A





n.	code
1	SBA0018104V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027636
17	S340514093A
18	SBC0000708
19	S340000193Z
20	S340004393Z
21	S332981393A
22	SBC0008060T
23	S340014293Z
24	S340174993Z
25	S332207492A
26	SBC0029464V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z
33	SBC0027769V
34	S340002693Z

IDM-51005703200





n.	code	
1	S340010492Z	
2	S321205693A	
3	SBA0005198	
4	SBC0008057T	
5	SBC0007940	
6	S321032098A	
7	SBC0007951	
8	S340083093Z	
9	S320699093A	
10	SBC0008060T	
11	S340028093Z	
12	S331802593A	
13	S332950700A	
15	S4304890ZZZ	
16	S340032993Z	
17	S340032993Z	
18	SBA0009893*	
19	S3401051ZZZ	
20	S340028393Z	
21	S340012393Z	
22	SBC0009454T	
23	S340024293Z	
24	SBA0009892*	
25	S332950400A	
26	S340058493Z	
27	SBC0008523T	
28	SBC0008524T	
29	SBA0005213	
30	S340006293Z	
31	SBA0009201	
32	SBC0014327T	
33	S340180493Z	
34	S340005893Z	
35	S3311811ZZZ	
36	S340018892Z	
37	S310227300A	
38	S340174993Z	
39	S332981200A	
40	SBC0000477	
41	S3400185ZZZ	
42	S332981192A	
43	S3400727ZZZ	
44	SBC0000478	
45	S321680700A	
46	S380827300A	
47	S332950800A	
48	S321680600A	
49	S332950592A	

51001701010




n.	code	
1	SBA0018103	
2	S340006193Z	
3	S340294592Z	
4	SBC0029465V	
5	SBC0029466T	

51001702500




IDM-51005703300

n.	code
1	SBA0007393
2	S340217593Z
3	SBA0007389
4	SBA0007372
5	S340006193Z
6	S340031893Z
7	SBC0012096
8	SBC0012101V
9	S340000393Z
10	SBC0012083T
11	SCA0000733
12	S340220492Z
13	S340316593Z
14	S340058493Z
15	SBC0012203T
16	SBC0012085
17	SBA0018055
18	S340000393Z
19	S332208592A
20	S332208492A
21	S320926498A
22	S370031898A
23	S340091093Z
24	S340012393Z
25	S340129293Z
26	SBA0018053V
27	S340039093Z
28	SBC0027636
29	SBC0012099
30	S340220292Z
31	S340014293Z
32	S340004393Z
33	S340042093Z
34	SBC0012110
35	S340223393Z
36	S340006293Z
37	S310195800A*
38	S320926993A
39	S332207592A
40	S332207492A
41	SBC0012103V
42	SBA0018060
43	S340514093A
44	S310071605Z
45	S340514093A
46	SBC0009914




n.	code	
1	S340010492Z	
2	S321205693A	
3	SBA0005198	
4	SBC0008057T	
5	SBC0007940	
6	S321032098A	
7	SBC0007951	
8	S340083093Z	
9	S320699093A	
10	SBC0008060T	
11	S340058493Z	
12	S340012393Z	
13	S332207292A	
14	SBA0006340	
15	SBC0030289	
16	S340061592Z	
18	SBC0010285T	
19	S340017593Z	
20	S340000293Z	
23	SCA0000887	
24	SBA0006348*	
25	S3400163ZZZ	
26	SBA0007389	
27	S3402906ZZZ	
28	SBA0006342	
29	SBA0006347	
30	SCA0000889	
31	SBC0012084V	
32	SBC0012108V	
33	S340011293Z	
34	SCA0000898	
35	SBC0009870T	
36	SCA0001080*	
37	SCA0000897	
38	SBC0010760T	
39	S340012393Z	
40	SBC0030294	
41	S340223393Z	
42	SBA0007370	
43	SBC0012106T	
44	SBC0012156	
45	SBA0006349*	
46	SBC0009866T	
47	SBC0009899T	

IDM-51005702900





n.	code	
48	S340031893Z	
49	S340002693Z	
50	S340025693Z	
51	S340220492Z	
52	SBC0009918T	
53	SBC0009867	
54	S340220392Z	
55	SBC0010284T	
56	SBC0009904T	
57	S310108548Z	
58	SBC0009868T	
59	S331710800B	
60	SBC0012098	
61	SCC0000116	
62	S340130592Z	
63	S340046893Z	
64	SBC0012097	
65	S3101260ZZZ	




n.	code	
1	SBA0007369	
2	S340017593Z	
3	S340041993Z	
4	S340003393Z	
5	SBC0012086T	
6	SBA0007368V	
7	SBC0011534T	
8	S340006193Z	
9	S340031893Z	
10	S340319193Z	
11	S340055893Z	
12	S340217593Z	
13	SBA0007155	
14	S340023593Z	

51001702700




n.	code	
1	SBA0007397	
2	S340217593Z	
3	SCA0000889	
4	SBC0012150T	
5	SBC0012153T	
6	SBA0007386V	
7	SBC0012133T	
8	S340174993Z	
9	S340023593Z	
10	S340017593Z	STD
11	S340057793Z	OPT
12	S3801095ZZZ	
13	S340344893Z	Ø1500
14	S340013592Z	Ø1650
15	SBC0012132T	Ø1800
16	SBA0007385	Ø2200


EM




M




M/NET




FM





SM




LP



n.	code
1	SBC0029860
2	SBC0029861
3	SBC0029862
4	SBC0029863
5	SBC0029864
6	SBC0029865
7	SBC0029873
8	SBC0006420
9	S300144499A
10	SBC0000708
11	SBC0012110
12	S300110096A
13	S300109396A




IDM 51005702500




IDM 51005702400

n.	code
1	SCC0001990 H63 C6 B5 S1 UL/CSA 220/240V
1	SCC0000096 H63 C6 B5 S1 3F 220/240V 50Hz 380/415V 50Hz 440V 60Hz
1	SCC0000097 H63 C6 B5 S1 3F 440V 50Hz
2	SCC0003376 H71C4 B5 220/415V 50Hz 3F UL/CSA
2	SCC0000843 H71 C4 0,55KW B5 230/415V-50HZ
2	SCC0000926 H71 C4 0,55KW B5 440V 50HZ 3F
2	SBA0018046 220/240-380415 50Hz Base HSD
2	SBA0018073 220/415V50HZ 3F UL/CSA Base HSD
2	SBA0018057 440V 50Hz Base HSD
3	SCC0001509 H63 C4 B14 3F UL 220/400V 50Hz
3	S380595900A H63 C4 B14 220/240V 50Hz 380/415V 50Hz
3	S380751100A H63 C4 B14 440V 50Hz
4	SCC0003584 220/415V 50HZ 3F UL/CSA
4	SCC0003576 220/415V 50HZ-440V 60HZ
4	SCC0003585 440V 50HZ 3F




n.	code	
1	S340000193Z	
2	S3400004393Z	
3	SCC00000577	
3	SCC00000546	
4	S340014293Z	

51001701300




IDM 51005700900


n.	code	
1	S440861640B	Ø 1500
1	S440862340A	Ø 1650
1	SBA0018140V	Ø 1800
1	SBA0011461V	Ø 2200




n.	code	
1	SBA0018117	
2	SCA0000495	
3	S340006293Z	
4	S340143592Z	
5	S340041693Z	
6	SBA0018276V	
7	SBC0005714T	
8	SBC0021305	
9	SBC0021756V	
10	SBC0029650	
11	SCA0000337	




n.	code
1	SBA0018118
2	SCA0000495
3	S340006293Z
4	S340143592Z
5	S340041693Z
6	SBA0018282V
7	SBC0005714T
8	SBC0021290
9	SBC0021756V
10	SBC0029661
11	SCA0000337




n.	code
1	SBA0018119
2	SCA0000495
3	S340006293Z
4	S340143592Z
5	S340041693Z
6	SBA0018289V
7	SBC0005714T
8	SBC0029666
9	SBC0021756V
10	SBC0029661
11	SCA0000337




n.	code
1	SBA0018122
2	S340001893Z
3	S340006293Z
4	S340531693A
5	S340049193Z
6	S340041693Z
7	S321686093A
8	S340530500A
9	S3802138ZZZ
10	S3802142ZZZ
11	S380828500A
12	S380828600A
13	SBA0018276V
14	SBC0021756V
15	SBC0029650
16	SBC0021305
17	S340513993A




n.	code	
1	SBA0018124	
2	S340001893Z	
3	S340006293Z	
4	S340531693A	
5	S340049193Z	
6	S340041693Z	
7	S321686093A	
8	S340530500A	
9	S3802138ZZZ	
10	S3802142ZZZ	
11	S380828500A	
12	S380828600A	
13	SBA0018282V	
14	SBC0021756V	
15	SBC0029661	
16	SBC0021290	
17	S340513993A	




n.	code	
1	SBA0018125	
2	S340001893Z	
3	S340006293Z	
4	S340531693A	
5	S340049193Z	
6	S340041693Z	
7	S321686093A	
8	S340530500A	
9	S3802138ZZZ	
10	S3802142ZZZ	
11	S380828500A	
12	S380828600A	
13	SBA0018289V	
14	SBC0021756V	
15	SBC0029661	
16	SBC0029666	
17	S340513993A	






n.	code	
1	SBA0018028	
2	SBA0018027V	
3	SBC0007325	
4	SBC0031247	
5	S340000393Z	
6	S340012393Z	
7	S340041293Z	
8	S340006293Z	
9	S340198493Z	



n.	code	
1	SBA0018120	
2	SBA0018197V	
3	SBC0001233	
4	SBC0031247	
5	S340000393Z	
6	S340012393Z	
7	S340041293Z	
8	S340006293Z	
9	S340198493Z	



n.	code	
1	SBA0018121	
2	SBA0018231V	
3	SBC0001250	
4	SBA0018231V	
5	S340000393Z	
6	S340012393Z	
7	S340041293Z	
8	S340006293Z	
9	S340198493Z	



n.	code
1	SBA0012440
2	S340183093Z
3	S340004393Z
4	S340012393Z
5	S340125093Z
6	S340016093Z
7	S340058493Z
8	S340065693Z
9	S3401337ZZZ
10	SBC0007798
11	SBC0016529T
12	SBC0020678T

IDM-51005701600