








n.	code
1	S340032493Z
2	S340065593Z
3	SBA0018389
4	SBC0026557
5	S340514093A
6	S340020693Z
7	S340107693Z
8	SBC0025244V
9	SBC0025212T
10	S340012393Z
11	S340028093Z
12	SBA0018467
13	S340052693Z
14	SBC0029083T
15	S340220592Z
16	S340012293Z
17	SBC0025182V
18	SBC0029804V
19	SBC0025285V
20	S340001893Z
21	S340006293Z
22	SBC0029270T
23	S340048693Z
24	S340016093Z
25	S340017593Z
26	S340000393Z
27	S340344893Z
28	SBC0025181V
29	S340220692Z
30	SBC0013996T
31	SBC0013997T



n.	code	
1	S340032493Z	
2	S340065593Z	
3	SBA0018389	
4	SBC0026557	
5	S340514093A	
6	S340020693Z	
7	S340107693Z	
8	SBC0025244V	
9	SBC0025212T	
10	S340012393Z	
11	S340028093Z	
12	SBA0018467	
13	S340052693Z	
14	SBC0029083T	
15	S340220592Z	
16	S340012293Z	
17	SBC0025182V	
18	SBC0029804V	
19	SBC0025285V	
20	S340001893Z	
21	S340006293Z	
22	SBC0029270T	
23	S340048693Z	
24	S340016093Z	
25	S340017593Z	
26	S340000393Z	
27	S340344893Z	
28	SBC0025181V	
29	S340220692Z	
30	SBC0013996T	
31	SBC0013997T	
32	SC0030764V	




n.	code
1	S340073593Z
2	S340342293Z
3	SCA0001941*
4	S340001893Z
5	S340006293Z
6	SBC0025206V
7	S340203293Z
8	S340065593Z
9	SBC0025205
10	S350051593Z
11	S340141993Z
12	SCA0000459
13	SBC0029266V
14	SCC0003270
15	S340051393Z
16	S340220392Z
17	SCC0003325
18	S380582600A
19	SCA0001940
20	SBC0025235T
21	S340012393Z
22	S340032493Z
23	S340067193Z
24	SBC0025187V
25	S340021993Z
26	S340000493Z
27	S340048693Z
28	S340000393Z
29	S340052793Z
30	S3804154ZZZ
31	SBC0026553V
32	SCA0001512
33	SCA0001942
34	SCC0000578
35	SBC0025185V
36	SCC0003325
37	S34028393Z
38	SBC0017180
39	SBC0025237T
40	SBA0015428V
41	S340299793Z
42	SBC0025190V




n.	code
1	SBA0017635
2	S340017593Z
3	S340002693Z
4	S340000393Z
5	S340012393Z
6	SCA0001206
7	S340000393Z
8	SBC0028693V
9	S340028093Z
10	S340005893Z

51002301500




n.	code	
1	SCA0000580	
2	S340021893Z	
3	SBC0014010T	
4	S340021893Z	
5	SBC0025215V	
6	SBA0015432V	
7	SBA0015430V	
8	SCA0000522	
9	S340028093Z	
10	S340012393Z	
11	SBC0005509	

51002300100




n.	code
1	SCC0003028
2	SBC0025259V
3	SCC0002992
4	SCC0003047
5	S340513993A
6	SBA0015437V
7	S340023593Z
8	S340017593Z
9	S340002693Z
10	S3403414ZZZ
11	SBC0029100T

51002300200




n.	code
1	SBC0026550T
2	S340065593Z
3	S340012393Z
4	S340000393Z
5	S350051593Z
6	S340141993Z
7	SCA0000550
8	SBC0026547T
9	S340003393Z
10	SBC0029102
11	SBC0029101T
12	SBA0016197V
13	S340043893Z
14	S340021993Z
15	S340033992Z

51002300301




n.	code
1	S340505900A Standard
1	SCA0001468 Antitraccia
1	SCA0000894 Per fondo abrasivo
2	S340505800A Standard
2	SCA0001471 Antitraccia
2	SCA0000895 Per fondo abrasivo
3	SCA0000458 Standard
3	SCA0001469 Antitraccia
3	SBA0006503 Per fondo abrasivo

51002300700





n.	code
1	S340511300A
2	S332635000A
3	S340001593Z
4	SBA0017646
5	SBC0027438T
6	S340031893Z
7	S340004393Z
8	S340022993Z
9	S340006193Z
10	S340514093A
11	S321635293A
12	S3403414ZZZ
13	S340017593Z
14	S340000293Z
15	S3403210ZZZ
16	SCA0000302
17	SBA0018393
18	SBB0004204
19	SBA0018266
20	SCC0001372
21	S3804911ZZZ
22	S340513993A
23	SBC0027543V
24	S340006293Z
25	S340223393Z



IDM 51002300401





n.	code
1	S340511300A
2	SBC0030701
4	SBA0019150
5	SBC0027438T
6	S340031893Z
7	S340004393Z
8	S340022993Z
9	S340006193Z
10	S340514093A
11	S321635293A
12	S3403414ZZZ
13	S340017593Z
14	S340000293Z
15	S3403210ZZZ
16	SCA0000302
17	SBA0018393
18	SBB0004204
19	SBA0018266
20	SCC0001372
21	S3804911ZZZ
22	S340513993A
23	SBC0027543V
24	S340006293Z
25	S340223393Z



n.	code
1	S471428200A
2	S340001993Z
3	S340017593Z
4	SBC0000501T
5	S340028093Z
6	SCA0000044
7	S331907681A
8	S310151200A*
9	S340000293Z
10	S332945592A
11	S332950093A
12	S3400238ZZZ






n.	code	
1	SBA0008112	
2	SCA0000108	
3	S340012393Z	
4	SBC0000500V	
5	SBC0000499T	
6	S340028393Z	
7	SBC0000502	



n.	code	
1	SBA0016954	
2	S3801649ZZZ	
3	SBC0027643V	
4	S340005193Z	
5	S340017593Z	
6	S3805202ZZZ	



51002301600

51002301701






n.	code	
1	S340010492Z	
2	S321205693A	
3	SBA0005198	
4	SBC0008057T	
5	SBC0007940	
6	S321032098A*	
7	SBC0007951	
8	S340083093Z	
9	S320699093A	
10	SBC0008060T	
11	S340058493Z	
12	S340012393Z	
13	SBC0008523T	
14	SBC0008524T	
15	SBA0005213	
16	S340006293Z	
17	SBA0009201	
18	S340028393Z	
19	SBC0014327T	
20	S340180493Z	
21	S340033593Z	
22	S3311811ZZZ	
23	S340018892Z	
24	S350240892Z	
25	S350235792Z	
26	S370025193Z	
27	S450544993Z	
28	S332306093A	
29	S4204333ZZZ*	
30	S4204333ZZZ*	
31	S4304892ZZZ	
32	S4304890ZZZ	
33	S4304890ZZZ	
34	S340040092Z	
35	S320282593Z	
36	S332347392A	
37	S3450006ZZZ	
38	S4304891ZZZ	
39	S310177700A	
40	S331910092A	

51002301800





n.	code	
1	SBA0014193V	
2	S320926498A	
3	S332208492A	
4	S332208592A	
5	S340012393Z	
6	S340129293Z	
7	S340028393Z	
8	S340091093Z	
9	S370031898A	
10	S310071605Z	
11	S332207592A	
12	S320926993A	
13	S310195800A	
14	S340006293Z	
15	S340223393Z	
17	S340002693Z	
18	SBC0027636	
19	S340000193Z	
20	S340004393Z	
21	S340514093A	
22	S340220292Z	
23	S340014293Z	
24	S340012393Z	
25	S332207492A	
26	SBC0027542V	
27	SCA0002198	
28	SBC0028129	
29	S340055893Z	
30	S340034193Z	
31	S340017593Z	
32	S340023593Z	

51002301901




n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057
5	SBC0007940
6	S321032098A*
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060
11	S340058493Z
12	S340012393Z
13	SBC0008523
14	SBC0008524
15	SBA0005213
16	S340224593Z
17	S340006193Z
18	SBA0001946
19	S332305981A
20	S340023493Z
21	S321007093A
22	S332306193A
23	S321006883A*
24	S4204332ZZZ*
25	SBC0009509
26	S3400156A
27	S340019192Z
28	S332306393A
29	S340010492Z
30	S320770393A
31	S4305046ZZZ
32	S310177700A
33	S340028393Z
34	SBC0009454
35	SBC0029352T
36	S340017793A

51002302000




n.	code	
1	SBA0007393	
2	S340217593Z	
3	SBA0007389	
4	SBA0007372	
5	S340006193Z	
6	S340031893Z	
7	SBC0012096	
8	SBC0012101	
9	S340000393Z	
10	SBC0012083	
11	SCA0000733	
12	S340220492Z	
13	S340316593Z	
14	S340058493Z	
15	SBC0012203	
17	SBC0029415V	
18	S340000393Z	
19	S332208592A	
20	S332208492A	
21	S320926498A	
22	S370031898A	
23	S340091093Z	
24	S340012393Z	
25	S340129293Z	
26	SBA0018053V	
27	S340039093Z	
28	SBC0027636	
29	SBC0012099	
30	S340220292Z	
31	S340014293Z	
32	S340004393Z	
33	S340042093Z	
34	SBC0012110	
35	S340223393Z	
36	S340006293Z	
37	S310195800A*	
38	S320926993A	
39	S332207592A	
40	S332207492A	
41	SBC0012103	
42	SBC0029416V	
43	S340514093A	
44	S310071605Z	
45	S340514093A	
46	SBC0009914	

51002302101





n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	S332207292A
14	SBA0006340
15	SBC0030289
16	S340061592Z
18	SBC0010285T
19	S340017593Z
20	S340000293Z
23	SCA0000887
24	SBA0006348*
25	S3400163ZZZ
26	SBA0007389
27	S3402906ZZZ
28	SBA0006342
29	SBA0006347
30	SCA0000889
31	SBC0012084V
32	SBC0012108V
33	S340011293Z
34	SCA0000898
35	SBC0009870T
36	SCA0001080*
37	SCA0000897
38	SBC0010760T
39	S340012393Z
40	SBC0030294
41	S340223393Z
42	SBA0007370
43	SBC0012106T
44	SBC0012156
45	SBA0006349*
46	SBC0009866T
47	SBC0009899T



IDM-51002302201



n.	code	
48	S340031893Z	
49	S340002693Z	
50	S340025693Z	
51	S340220492Z	
52	SBC0009918T	
53	SBC0009867	
54	S340220392Z	
55	SBC0010284T	
56	SBC0009904T	
57	S310108548Z	
58	SBC0009868T	
59	S331710800B	
60	SBC0012098	
61	SCC0000116	
62	S340130592Z	
63	S340046893Z	
64	SBC0012097	
65	S3101260ZZZ	





n.	code
1	SBA0007397
2	S340217593Z
3	SCA0000889
4	SBC0012150
5	SBC0012153
6	SBA0007386
7	SBC0012133
8	S340174993Z
9	S340023593Z
10	S340017593Z
11	S340057793Z
12	S3801095ZZZ
13	S340344893Z
14	S340013592Z
15	SBC0012132
16	SBA0007385





n.	code	
1	SBA0014193V	
2	S320926498A	
3	S332208492A	
4	S332208592A	
5	S340012393Z	
6	S340129293Z	
7	S340028393Z	
8	S340091093Z	
9	S370031898A	
10	S310071605Z	
11	S332207592A	
12	S320926993A	
13	S310195800A	
14	S340006293Z	
15	S340223393Z	
16	SBC0027769V	
17	S340002693Z	
18	SBC0027636	
19	S340000193Z	
20	S340004393Z	
21	S340514093A	
22	S340220292Z	
23	S340014293Z	
24	S300144499A	
25	S332207492A	
26	SBC0027542V	
27	SCA0002198	
28	SBC0028129	
29	S340055893Z	
30	S340034193Z	
31	S340017593Z	
32	S340023593Z	

IDM-51002302700




n.	code
1	S340180493Z
2	S340028393Z
3	S340006193Z
4	S340012393Z
5	S340006293Z
6	S340058493Z
7	S340032993Z
8	S340033593Z
9	S3311811ZZZ
10	S331910092A
11	S340018892Z
12	S350235792Z
13	S350240892Z
14	S350265000A
15	S370025193Z
16	S4204190ZZZ
17	S4204333ZZZ
18	S4304890ZZZ
19	S4305051ZZZ
20	S450544993Z
21	SBA0005213
22	SBA0009201
23	SBC0008523T
24	SBC0008524T
25	SBC0014327T




IDM-51005700800

n.	code	
1	SBA0009961	
2	S340010492Z	
3	S340090293Z	
4	S340038293Z	
5	S320699093A	
6	S321205693A	
7	S321256098A	
8	S340083093Z	
9	SBA0005198	
10	SBC0008060T	
11	SBC0011559T	
12	SBC0011560	
13	SBC0011879T	
14	SBC0011882	
15	SBC0011883	
16	SBC0011885	
17	SBC0011887T	
18	SBC0011888	
19	SBC0011889T	
20	SBC0029978	
21	SCA0001050	

[illegible]




025 01




n.	code
1	SCC0000842 <i>Batterie acide</i>
1	S380755500A <i>Batterie gel M - FM</i>
1	S380761900A <i>Batterie gel LP</i>
1	SCC0003397 <i>Batterie al litio</i>

51002300800




51002301000

n.	code
1	SCC0000842 <i>Batterie acide e gel</i>
1	SCC0003298 <i>Batterie al litio</i>
2	SCC0003410 <i>Batterie acide e gel 220/240V</i>
2	SCC0003411 <i>Batterie acide e gel 115V</i>
2	SCC0003399 <i>Batterie al litio</i>



51002302400

n.	code	
1	S340000193Z	
2	S340004393Z	
3	SCC0000577*	STD
3	SCC0000546*	OPT
4	S340014293Z	
5	SBC0012085V	STD
5	S321077300A	OPT



51002301100

n.	code	
1	SBC0004209	STD
1	SBB0004208	ULCSA